

## REMOVE DUST ON TECHS FOR THAT TIPTOP SHINE

GET THE TIPS  
GADGET

## INSTRUCTIONS

1.



Spray WD-40 Specialist® Air Duster in short even bursts to thoroughly remove dust and debris from the exterior.

2.



Using the soft brush, and work around it for a clean sweep.

3.



Take the cotton swab go into any tight corners to remove any micro debris.

4.




Go one more round with WD-40 Specialist® Air Duster overall around your gadget for a clean final blast.

*Tip! We don't recommend using WD-40 Specialist® Air Duster for cleaning the sensor to prevent any damage.  
Great for: Camera, Computers, Printers, Laptop, Keyboards, Photo Equipment, Scanners, Watches and Clocks,  
Copiers, Phones, Stereos and Scientific and Lab Equipment.*


## WHAT YOU NEED



x1



x1



x1

Scan For More Info

**WD-40**

**WD-40 SPECIALIST® AIR DUSTER +  
SOFT BRUSH + COTTON SWAB**